



# MEASUREMENT REPORT



Customer: WHITEHALL INDUSTRIES  
Operator: Felipe Martinez  
E-mail: felipe.martinez@mess.com.mx  
Workspace: PROGRAM\_MARZO  
Project: G3711A\_30027675LH - pieza 2

Part name: G3711A  
Part number: 30027675LH  
Drawing : S/R  
Device: MESS-BRAA-003





## Feature Table

Length Units Millimeters

### TH#1

Control	Nom	Meas	Tol	Dev	Test
X	1375.352	1375.352	±0.050	0.000	Pass
Y	-500.950	-500.950	±0.050	0.000	Pass
Z	989.011	989.011	±0.050	0.000	Pass

### TH#2

Control	Nom	Meas	Tol	Dev	Test
X	1629.352	1629.373	±0.050	0.021	Pass
Y	-500.950	-500.950	±0.050	0.000	Pass
Z	989.011	989.011	±0.050	0.000	Pass

### TH#3


Control	Nom	Meas	Tol	Dev	Test
X	1375.352	1375.352	±0.050	0.000	Pass
Y	-310.450	-310.484	±0.050	-0.034	Pass
Z	989.011	989.011	±0.050	0.000	Pass

Customer: WHITEHALL INDUSTRIES  
Operator: Felipe Martinez  
E-mail: felipe.martinez@mess.com.mx

Part name: G3711A  
Part number: 30027675LH  
Piece: pieza 2







## Comparison Point Table

Units Millimeters

### NET-B-1

Control	Nom	Meas	Tol	Dev	Test
Surface Distance		-0.448	±1.000	-0.448	Pass

### NET-B-2


Control	Nom	Meas	Tol	Dev	Test
Surface Distance		-0.187	±1.000	-0.187	Pass

Customer: WHITEHALL INDUSTRIES  
Operator: Felipe Martinez  
E-mail: felipe.martinez@mess.com.mx

Part name: G3711A  
Part number: 30027675LH  
Piece: pieza 2



3D Scene Caption



### Comparison Point Table

Units Millimeters

**NET-0- SPC-1**

Control	Nom	Meas	Tol	Dev	Test
Surface Distance		-0.035	±0.100	-0.035	Pass

**NET-0- SPC-2**

Control	Nom	Meas	Tol	Dev	Test
Surface Distance		-0.033	±0.100	-0.033	Pass


**NET-0- SPC-3**

Control	Nom	Meas	Tol	Dev	Test
Surface Distance		0.013	±0.100	0.013	Pass

Customer: WHITEHALL INDUSTRIES  
 Operator: Felipe Martinez  
 E-mail: felipe.martinez@mess.com.mx

Part name: G3711A  
 Part number: 30027675LH  
 Piece: pieza 2





## Feature Table

Length Units Millimeters

Name	Control	Nom	Meas	Tol	Dev	Test
DATUM-C-	X	1451.831	1451.789	±0.050	-0.042	Pass
	Y	-412.400	-412.470	±0.100	-0.070	Pass
	Z	1111.775	1111.767	±0.100	-0.008	Pass
STAB-1	X	1246.035	1245.981	±0.100	-0.054	Pass
	Y	-411.700	-411.654	±0.100	0.046	Pass
	Z	1088.800	1088.800	±0.100	0.000	Pass
STAB-2	X	1694.301	1694.393	±0.100	0.092	Pass
	Y	-411.700	-411.620	±0.100	0.080	Pass
	Z	1116.300	1116.300	±0.100	0.000	Pass
STAB-3	X	1137.031	1136.949	±0.100	-0.082	Pass
	Y	-371.200	-371.293	±0.100	-0.093	Pass
	Z	1081.336	1081.323	±0.100	-0.013	Pass
STAB-4	X	1765.000	1764.938	±0.100	-0.062	Pass
	Y	-372.866	-372.839	±0.100	0.027	Pass
	Z	1121.675	1121.677	±0.100	0.002	Pass

Customer: WHITEHALL INDUSTRIES  
Operator: Felipe Martinez  
E-mail: felipe.martinez@mess.com.mx

Part name: G3711A  
Part number: 30027675LH  
Piece: pieza 2

